



PRODUCT BULLETIN

3" Monitor Flange Connection Change


In response to customer feedback regarding the recent change combining the 3" flanges into a single flange with ANSI and DN bolt hole patterns, a design change has been made to separate 3" monitor connection flanges to the original single-pattern configurations.

The following TFT monitor product lines are affected:

Tornado [®]	Crossfire [®]
Monsoon [®]	Hurricane [™]
Typhoon [™]	Protector [™]

CURRENT DESIGN
Through 10/31/2022

UPDATED DESIGN
Beginning 11/1/2022



TASK FORCE TIPS LLC
MADE IN USA · tft.com

3701 Innovation Way, Valparaiso, IN 46383-9327 USA
800-348-2686 · 219-462-6161 · Fax 219-464-7155