


BELLEVILLE WASHER
ORIENTATION



LXH-002

PARTS LIST: HEMISPHERE I-BEAM CLAMP
MAINTENANCE AND SERVICE

SHEET:
1 of 2

REV:

DATE: 8/18/20



TASK FORCE TIPS, LLC.
3701 INNOVATION WAY
VALPARAISO, IN 46383 USA
(219)462-6161

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	HE160	MOUNTING CLAMP BACKBONE	1
2	HE102A	CLAMP MOUNTING BASE	1
3	HE175	LATCH PIN	1
4	HE178	CAPTURED MOUNTING PIN	1
5	HM770	DETENT SPRING	1
6	HE134	WEAR STRIP	4
7	HE176	5/8" THREADED ROD	1
8	HE182	CLAMP WEDGE	1
9	HE184	ADJUSTER PIVOT	1
10	HE133	FIXED ADJUSTMENT PIVOT	1
11	HE187	PIN RETAINER	2
12	HE803	CRANK WITH KNOB SUBASSEMBLY	1
13	HE183	CLAMP SLIDE	1
14	HE188	CAPTURED BLOCK PIN	1
15	HM770	DETENT SPRING	1
16	VT31-18SS375	5/16-18 X 3/8 SOCKET SET SCREW CUP POINT	1
17	HE175	LATCH PIN	1
18	HE195	TASK FORCE TIPS LOGO LABEL	2
19	HE134	WEAR STRIP	4
20	VM4904	BELLEVILLE SPRING LOCK WASHER	4
21	VT25-20BH1.0	1/4-20 X 1.0 BUTTON HEAD CAP SCREW	1
22	VT25-20BH1.2	1/4-20 X 1.25 BUTTON HEAD CAP SCREW	1
23	VW500X265-63	WASHER	1
24	HE182	CLAMP WEDGE	1
25	HE188	CAPTURED BLOCK PIN	1
26	HM770	DETENT SPRING	1
27	HE175	LATCH PIN	1
28	VT31-18SS375	5/16-18 X 3/8 SOCKET SET SCREW CUP POINT	1
29	HE134	WEAR STRIP	4
30	XXL505	PLUNGER	2

LXH-002

PARTS LIST: HEMISPHERE I-BEAM CLAMP

MAINTENANCE AND SERVICE

SHEET:
2 of 2

REV:

DATE: 8/18/20



TASK FORCE TIPS, LLC.
3701 INNOVATION WAY
VALPARAISO, IN 46383 USA
(219)462-6161