



PRODUCT BULLETIN

Crossfire[®] and Hurricane[™] Shaft Seal Change

A design change has been made to the lower seal on the shaft of all Crossfire monitors, and manually operated Hurricane monitors.

The molded external cover boot (TFT part # X240) is replaced with an internal O-ring.

CROSSFIRE MONITOR

MANUALLY OPERATED HURRICANE MONITOR



**PREVIOUS DESIGN
THROUGH 9/2021**

**UPDATED DESIGN
AFTER 9/2021**



Features and Benefits	
Internal O-ring	Improved Shaft Sealing
	Not exposed to UV rays/degradation
	Will not move out of place

TASK FORCE TIPS LLC
MADE IN USA · tft.com

3701 Innovation Way, Valparaiso, IN 46383-9327 USA
800-348-2686 · 219-462-6161 · Fax 219-464-7155